



ADMINISTRATION BUILDING

Trumansburg Central School District		System or Component Description	Last Major Reconstruction / Replacement (year)	Probable Useful Life	Remaining Useful Life	Building System Ratings					5-Year Plan Cost Magnitude	District Priority Ranking	Recommendations	PRIORITY		
SED SYSTEM NUMBER	BCK ITEM NUMBER					Item	E	S	U	NF				CF	1	2
	104	Other	Original one door/ Metal clad insulated.	1985	20	0		X			\$6,900		Furnish and install (1) FRP door and hardware. Completed 2007	X		
	157	Carpet	Yes	1990	15	0		X			\$11,200		Carpet needs replacement. Partial replacement 2007		X	
	209	Computer - Classroom network drops	CAT 5 jacks in office areas		15			X			\$3,000		Additional jacks needed, possibly wireless in conference area			X
	216	Other	LCD projector in conf room								\$6,300		There is a need for a permanent mount, motorized LCD projector in auditorium area, using exg screen for presentations and LGI.			X
	218	Fluorescent, T8 or T12	Fixtures are fluorescent T - 12.	1990	25	10		X			\$3,300		Replace all T12's with energy efficient T8's throughout Completed 2008	X		
	382	Fire Alarm Main Panel	N/A.		20			X			\$15,000		Provide 4 zone panel with smoke detectors and A/V units through-out building to increase life safety Completed 2010		X	
	409	Emergency Lights - Wall Pack w/ battery	N/A.		20			X			\$800		Emergency lighting required to illuminate all paths of egress	X		

TOTAL 5 YEAR PLAN COST MAGNITUDE = \$46,500